Annexure D

В	UILDING SAF	ETY CERTIFIC	ATE		
			Date	d: 05-06-	2025
1. Gair	rdkhal,	Yamkes	hwar Po	euri Garl	e of the
Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
04	04	06	02	02	02
	existing by address) is h	existing building .A.U. Gaindkhal, address) is having block(s)	existing building .A.U.G.I.C	existing building AUGIC Gaindkhal Gaindkhal Yamkeshwar Paraddress) is having block(s)/Floor(s) as per details below. Block Block Block Block Compared to the second se	existing building AUGIC Gaindkhal (name) Gaindkhal Famkeshwar Pauri Garlendress) is having block(s)/Floor(s) as per details below: Block Block Block Block Block Block Company Comp

The building is owned/occupied by Atal Utknist Govt Inter College Gaindhollname of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Ranal Works Deformation of Department/ Govt.) on.05 June 2025...(date of inspection) in the presence farth barthy Kala and Raypal Singh. (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for with rule and subject to compliance of the specific conditions as appended.

1.

2.

3.

4.

Issued on \$5-06-2025 at Gainelkhal by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :_

Name: Vipin Gang

Designation: And Land Engineer

Name & Address of Department/ Office: _ Q L L D

ASS STANT ENGINEER RURAL WORKS DEPARTMENT

DIVISION KOTOWARA

65 | Page